

**PRODUCT: DSx™ 264 and DSx 300 RECORDING AND STREAMING CODECS****TITLE: VERSION 2.3.3.0 RELEASE NOTES**

DATE: 7 September 2016

**NEW FEATURES**

The Version 2.3.3.0 feature set is unchanged from Version 2.3.2.0.

**NEW/CHANGED COMMANDS**

The Version 2.3.3.0 command set is unchanged from Version 2.3.2.0.

**RESOLVED ISSUES**

This release resolves the following issues:

- Corrected an issue that caused encoding to stop after a long period of continuous operation (typically eight (8) days or more). It is no longer necessary to power-cycle the unit to recover from this condition. (2145)
- Corrected an issue that prevented the Web Control Panel (WCP) from displaying the Video Output Timing parameters (on the **Output** tab) when in Decode mode. (2123)

**KNOWN ISSUES**

- When encoding stops due to the error condition described above, there is a delay of approximately 20 seconds before encoding automatically resumes. (2145)

**FIRMWARE UPDATE**

Please refer to the User's Guide for your DSx product model for detailed firmware update instructions.

**FIRMWARE, FPGA, WCP, AND NIOS VERSIONS**

<b>Firmware:</b>	<b>2.3.3.0</b>
<b>FPGA:</b>	<b>0.0.3.0</b> (unchanged from previous version)
<b>WCP:</b>	<b>2.3.1.0</b> (unchanged from previous version)
<b>NIOS:</b>	<b>9</b> (unchanged from previous version)