RGB SPECTRUM

Release Notes

Product	MediaWall 2000

IMPORTANT NOTE:	**Please read this section before performing a firmware upgrade.** Anomalies with general operations or a firmware upgrade may occur if the compact flash card is not installed. For correct operation please be sure to have a compact flash card inserted in the MediaWall 2000 front panel compact flash slot prior to performing a firmware upgrade or using the product.
VERSION:	1.01
PART # / CSUM:	
COMPATIBILITY:	Requires hardware version 1.20 or later
NEW FEATURES:	Pre-defined window layouts Horizontal overlap WCP now allows window movement using arrow keys
CHANGES/FIXES:	**The following changes/fixes are included in this release**. Problem with WCP overwriting timing list entries has been fixed. WCP accepted "Show Timing Values" checkbox to be selected when outside of the checkbox. The active area has been reset to exclude the excessive area. Corrected a problem with WCP I/O timing text color which showed when red when the "Show Timing Values" check box was unchecked on an empty entry. Locked out WCP adjustment of interactive timing when "Show Timing Values" checkbox was checked. Disabled WCP deletion of output timing values when "Show Timing Values" checkbox was checked. WCP now disables sync format editing when edit box is unchecked. Corrected a problem with video window source rectangles which unzoomed at start up regardless of prior state. Corrected a problem with interactive timing adjustments which worked in the reverse sense. Corrected a problem with image wrapping when switching DVI window on/off. Now preserves Output timing names with SETTINGSIMPORT. Improved video sharpness when video bridged over H mullion. Resolved a problem with image break up with 1280x960 85 Hz output resolution. Input vertical frequency is now reported correctly Corrected a problem with window priorities that affected windows with priority 11 and 12. Removed Output fade to black function. Removed window fade to background function.
RELEASE DATE	2/6/2006