



RGB Spectrum, Inc.  
950 Marina Village Parkway  
Alameda, CA. 94501  
Tel: 510-814-7000 Fax: 510-814-7026

## **Firmware 1.1 Release Notes for Linx DVI 8X8 Matrix Switcher May 2008**

Firmware version 1.1 includes the following changes:

- Front panel correctly updates when the baud rate is changed.
- Independent enable/disable buttons have been added to the I/O matrix of the web control panel. These are described in the Routing Window section of the User's Guide Operation chapter.
- Control-Z may be used on the WCP to undo the one operation: either a loaded preset or route one input to all outputs (right mouse click). The mouse cursor must be placed within the routing matrix borders.

Notes:

- The User's Guide now indicates the correct depth of the Linx Switcher as 12.5 inches.
- Do not use the delete key when making command line entries.
- Windows font size should be set to Normal (96 DPI) for correct display of the WCP. To verify this setting:

Select **Display** from the Windows **Control Panel**.

Click on the **Settings** tab.

Click on **Advanced**.

Select **Normal (96 DPI)**.

For instructions on updating firmware see the *Linx DVI 8X8 Matrix Switcher User's Guide*.